

1.1

SHEREVEPORT SUBDIVISION March Safety Meeting

ATTENDANCE:

Phillip Miller-Trainmaster
Brandon Goodman- Engineer Transportation/Local President BLET
Scott Pickett- Conductor Transportation
John Rymer-Roadmaster MOW
Furman Gilmore-FOE
Sam Yosten-Engineer Transportation
Scoot Sowell-Plant Manager ST@T

1.2

OLD BUSINESS:

- 1- Radio problems at Wade-Repeater will be installed within the next 2 months-Still waiting
- 2-Installing a Rock walkway at the Dollar Store-Walkway is installed
- 3-Installing a rock walkway at the TEXAS WYE-Rock is marked and ready for installation
- 4-Crossing Bungalows need better location markers-waiting on a response from the signal department-
No one from signal department was present.
- 5-PTI cell phone policy-no one from PTI was at the meeting
- 6-Signal at 523 needs to be adjusted to show a medium approach so we will know if we are meeting a train-No one from Signal department was present
- 7-Discussed having wheel chocks available at Wade-Marty has installed them at Wade
- 8-Marty Robinett is in need of a handheld radio to better communicate with train crews-Has not received a radio
- 9-North Bridge at Wilton is rough
- 10-Detector at MP 441 going Southbound is weak
- 11 -Whistle boards at Wilton at Northbound in the siding cannot be seen when meeting another train
- 12-County Road 18 Milepost has private crossing signs,it may need whistle boards installed
- 13-Need Signal Department to check and see if the signal at Ogden can have the timing changed to show a clear signal instead of a medium approach-signal Department was not present
- 13-WX board missing for Main Street southbound at Rich Mountain is missing

New Business:

- 1-Tree has fallen at Hatfield

- 2-Private crossing N Bound around Sandra is missing
- 3-Bridge just past North Wilton is rough-John will look into it.
- 4-FOE Gilmore discussed glitches in some of Locomotives software
- 5-Southbound WX at Whatley missing
- 6-Milepost 340 Northbound WX Owen Lows is missing
- 7-WX board Southbound Main street at Rich Mountain missing
- 8-Discussed removing P signs of off signals now that they are not required
- 9-milepost 350 is down

To take advantage of this template's design, use the Styles gallery on the Home tab. You can format your headings by using heading styles, or highlight important text using other styles, like Emphasis and Intense Quote. These styles come in formatted to look great and work together to help communicate your ideas.

Go ahead and get started.